CLASSIFICATION		
COUNTRY		
TOPIC Bautzen-Litten Airigela	m, ta	
EVALUATION PLACE OBTAINED	R MIN / A PAR STEEL SEE	
DATE OF CONTENT	-	
DAVE PREPARED ? December 1954		
ACFERENCES		
PaGES 4 ENCLOSURES (No. & TYPE) 2 - two sketches or ditto, with sevend		
This is UNEVALUATED Information	nganggalan di ndibigai sebani di se	
19 October. Between 0800 and 1500, individual Yak-lis made cross-country flights. Possibilities of observation were limited.	25X1 25X1	
	25 X 1	
22 October. Between 0800 and 1600, some formations of three Yak-lis crossed over the town. 23 October. Between 0800 and 1800, elements of two aircraft made cross-country flights. At 1845, one Yak-li banked over the town.	25 X 1	
	25 X 1	
26 October. Between 0800 and 1500, Yak-lls practiced flying. Between 1300 and 1350, the following detailed observations were made at the field: Between 1330 and 1333, three Yak-lis took off at intervals of 1 minute. Two of the aircraft subsequently disappeared toward the west while the third aircraft headed toward the west after	25 X 1	
malain a Rosal Clicky to 1740 and at 1744 simon of	25 X 1	
the straight of the first secretary and straight of the straig	25X1	
OLASSITICATION SECRET		

25X1

25X1

SECRES

25X1

- 2 .

determined at which point the hose of the tank trucks connected to the tanks of the Yak-lls.

27 October. No air activity was observed.

28 October. At 1000, an element of two Yak-lis was seen over the town.

29 October. Between 0900 and 1500, mainly formation flying was practiced. At 0900, six Yak-lis were seen over the town at distances of helf a minute heading toward the west. At 1115, a formation of 10 Yak-lis was seen aloft over the town. At 1300, a formation of 10 Yak-lis crossed over the town from the direction of the field. The formation returned from the west at 1305, crossed over the field toward the east and returned to the field at 1317. The formation dispersed over the town and the aircraft landed individually.

30 October. Elements of two Yak-11s made cross-country flights.

31/to 6 November. No air activity was seen from the town.

- 2. Several new buildings were under construction in the eastern section of Bautzen. One building located opposite the corner of Thomas-Mann Strasse and Fauli Strasse was completed and occupied by VFL.
- It could not be determined whether the barracks which previously housed the construction staff here still occupied.
- 4. No changes were observed on the radio installation southwest of the flight control station. The installation consisted of 5 masts 5 to 6 meters high. Four masts were arranged in a square and the fifth mast was north of the square. A tent was in the middle of the square of masts. During air activity, another mast about 8 meters high was repeatedly observed about 20 meters southwest of the installation.
- 5. The southern wall around the field began at kilometer marker 5.2, and terminated at kilometer marker 5.45 where it rurned to the north. The western wall beginning at kilometer marker 3.2, extended to the northwest for 350 meters and, at a right angle, turned to the east until a point of a perpendicular line raised at kilometer marker 3.2. From this point the boundary continued as a wire fence to the northwest as far as the western end of the runway. From there, the fence continued parallel to and at a distance of about 150 meters from the road to Kreckwitz. The northern and eastern edges of the landing field were also surrounded by a wire fence. The grass-covered area north of triangulation point 164.7 and northwest of kilometer marker 5.25 was not fenced in.

The fuel dump in the southwestern corner of the field was surrounded by a wall to the south, vest and northwest and by a wire fence along the landing field. Four containers were observed at a right angle to the wall. Further, there were 3 tower-like burkers and a wooden watch

SECRUT

SECRET, 25X1

tower. The fuel dump had a special entrance from the read passing along the southern edge of the dump. Slightly east of the entrance to the dump was the main entrance to the airfield. This main entrance road extended to a small building which previously was believed to be a guardhouse and now was recognized as transformer station. A small temporary brick building was located southwest of the flight control station and the hangars were located northeast of the flight control building. Four new hangars of wooden and mixed construction were observed just north of the wall on both sides of the road which extends north of triangulation point 170.1 toward the landing field. A temporary building was east of these hangars. Five buildings were located east of the latter building and parallel to the wall. A second transformer station was observed in New Purschwitz just northwest of triangulation point 170.1. The runway extended in a different direction from that of the previous assumption: The eastern end was located farther south while the western end was in a depression and could not be definitely observed. The dispersal area was at the eastern end of the runway and taxiway and extended about 120 meters to the north. The runway was about 50 meters wide. No observations were made indicating concreting work on the runway. No surveying or excavation work was observed. Two concrete mixers were still located north of the main entrance. Excavation work was under way just east of the southwestern corner of the wall where the wire fence began. A semi-circular embankment open to the south and with an inner width of about 20 meters was under construction there.

A new road ran in a curve east of the field and connected Purschwitz with the national highway south of the field. This was the by-pass road between Neu Purschwitz and Furschwitz and replaced the former road running across the airfield. 2

6.	25X1

- 7. Between 0930 and 0945 on 29 October, it was observed from quite a distance that 12 local flights were made by Yak-lls at an altitude of about 250 meters. Four Yak-lls circled over the field at 1130 and a formation of 10 Yak-lls was seen at 1300. The distance and interval between the individual aircraft flying in formation was 2 to 5 wing spans. At 1000, 1200 and 1335 on 30 October, a large number of Yak-lls practiced formation flying. Between 31 October and 5 November, no air activity was observed. On the days when no air activity was conducted, the two single-mast antennas were not observed.
- 8. A vanglike truck which, during air activity, was repeatedly observed on the landing field, was parked in the yard of Husaren Kaserne. A disk which could rotate in a horizontal direction was mounted on the vanglike superstructure. Two loudspeaker-like devices were fitted in the middle of the disk and opposite each other. When the truck was parked on the landing field, the disk with the devices on top slowly rotated in a horizontal direction.

9.	At about 1300 on	4 November, truck	occupied by 30 men,	25 X 1
	left the airfield	and proceeded towar	d Husaren Kaserne.	

SECRET,

SECRET

	·· 4 ··	25 X 1
lo.	The former Husaren Kaserne in Bautzen, located on Kaethe Kollwitz Strasse at the corner of Stralauer Strasse, was still occupied by members of the Aeroclub.	25X1
11.	The building on Pauli Strasse in Bautzen was occupied by 60 to 80 unmarried officers of the Aeroclub. No field grade officers were seen there. The FdJ flag was fitted on top of the building. 4	
12.	The following motor vehicles were observed in the area of the Husaren Kaserne:	
	Sedans Trucks	25X1
1.[Comment. It is believed that the 2d and 3rd Ens of the Aeroclub Bautzen are still stationed at Bautzen-Litten airfield. The observed air activity including formation flights with up to 10 Yak-lls indicates that progress is being made by the pilots here.	25X1
2.[Comment. The purpose of the 3 overground bunkers in the fuel dump is unknown. For sketch of bunkers, see Annex 1. For layout sketch of airfield, see Annex 2.	25 X 1
3.	Comment. The radio truck mounting a horizontal disk with antenna system presumably serves for the control of air activity over the field.	25 X 1
4.	Coment. The information that members of the Aeroclub are housed in the Husaren Kaserne and in the Home for Bachelors in Bautzen was received previously.	25X1

SECRET

Approved For Release 2008/01/08 : CIA-RDP80-00810A005700530001-3

Overground Concrete Structures in the Fuel Dump

Annex 1


at Bautzen-Litten Airfield

SECRET

. 25X1

25X1

Approved For Release 2008/01/08 : CIA-RDP80-00810A005700530001-3



SECRET

arine.	2	

25X1

25X1

Bautzen-hitten Airfield

τ		3	
ьe	, е	na	

. .. .

Å.	Lain	enti	ranc	е
2	The + me		4.0	43.

- Entrance to fuel dump
- Tatch tower
- Overground round concrete structure
- Overground four-edged concrete structure
- 6 Construction site with earth embankment
- Four buildings presumably used as quarters
- Two concrete mixers 8
- Transformer station
- 10 Temporary building
- Flight control building 11
- 12 Five hangars
- 33 Five buildings
- Radio installation of 5 masts 14
- location of single-mast radio installation during air activity 15
- 16 Taxiway
- 17 Eunway
- Parking lot of motor vehicles, including radio truck. fire truck. 18 2 tank trucks
- 19 Dispersal area
- 20 Wall
- Tire fence 21

	25X1
	20/(1

SECRUT,